



**Free Questions for 300-615 by vceexamstest**

**Shared by Elliott on 24-05-2024**

**For More Free Questions and Preparation Resources**

**Check the Links on Last Page**

# Question 1

---

Question Type: MultipleChoice

---

Refer to the exhibit.

```
Unable to change server power state-MC
Error(-20): Management controller cannot or
failed in processing
request(sam:dme:ComputePhysicalTurnup:Execute
)

[ help ]# power
OP:[ status ]
Power-State:          [ on ]
VDD-Power-Good:       [ active ]
Power-On-Fail:        [ inactive ]
Power-Ctrl-Lock:      [ unlocked ]
Power-System-Status: [ Good ]
Front-Panel Power Button: [ Enabled ]
Front-Panel Reset Button: [ Enabled ]
OP-CCODE: [ Success ]
[ power ]#
```

An engineer monitors a Cisco UCS server logs and discovers a blade discovery issue. Which procedure resolves the issue?

**Options:**

---

- A-** 1. Verify the server power module.  
2. Decommission the faulty module.  
3. Insert a new power module.  
4. Recommission the new module.
- B-** 1. Verify that server platform power is failed  
2. Resolve the platform power issue.  
3. Reboot the server.  
4. Recommission the server.
- C-** 1. Verify the FSM status on the server.  
2. Decommission the impacted server.  
3. Reset the slot where the server is located.  
4. Recommission the server.
- D-** 1. Verify that the power on self-test operation is failed.  
2. Verify that the server firmware is corrupted.  
3. Decommission the server firmware  
4. Recommission the server with new firmware.

**Answer:**

---

C

## Question 2

---

**Question Type:** MultipleChoice

---

Refer to the exhibit.

```
Booting kickstart image: bootflash:/installables/switch/ucs-6100-k9-kickstart.4  
.1.2.N2.1.11.bin....Loader Version pr-1.3
```

```
loader> dir  
bootflash:  
  lost+found  
  ucs-6100-k9-kickstart.4.1.3.N2.1.11.bin  
  ucs-6100-k9-system. 4.1.3.N2.1.11.bin  
  sysdebug  
  chassis.img  
  nuova-sim-mgmt-nsg.0.1.0.001.bin  
  pnuos  
  installables  
  mts.log  
  vdc_2  
  vdc_3  
  vdc_4  
  distributables  
  initial_setup.log  
  tmp  
  .tmp-kickstart  
  .tmp-system  
  
loader>
```

A Cisco UCS Fabric Interconnect fails during the upgrade process. The working images of the fabric interconnect are stored on the bootflash. Which set of commands recovers the fabric interconnect?

### Options:

---

A- loader> dir

```
loader> boot ucs-6300-k9-kickstart.5.0.2.N1.3.02d56.bin
switch(boot)# init system
switch(boot)# reload
switch(boot)# load ucs-6300-k9-system.5.0.2.N1.3.02d56.bin
```

**B-** loader> dir

```
loader> boot ucs-6300-k9-kickstart.5.0.2.N1.3.02d56.bin
switch(boot)# copy ics-manager-k9.1.4.1k.bin nuova-sim-mgmt-nsg.0.1.001.bin
switch(boot)# boot ucs-6300-k9-system.5.0.2.N1.3.02d56.bin
```

**C-** loader> dir

```
loader> boot ucs-6300-k9-kickstart.5.0.2.N1.3.02d56.bin
switch(boot)# init system
switch(boot)# reload
switch(boot)# boot ucs-6300-k9-system.5.0.2.N1.3.02d56.bin
```

**D-** loader> dir

```
loader> boot ucs-6300-k9-kickstart.5.0.2.N1.3.02d56.bin
switch(boot)# copy ics-manager-k9.1.4.1k.bin nuova-sim-mgmt-nsg.0.1.001.bin
switch(boot)# load ucs-6300-k9-system.5.0.2.N1.3.02d56.bin
```

**Answer:**

---

D

## Question 3

---

**Question Type: MultipleChoice**

---

A network engineer experiences the error "DDR3\_P1\_B1\_ECC" when upgrading Cisco UCS firmware. Which action resolves the issue?

**Options:**

---

- A- Reset the DIMM
- B- Reset the BMC firmware
- C- Reflash the controller firmware
- D- Reflash the DIMM

**Answer:**

---

A

## Question 4

---

**Question Type: MultipleChoice**

---

Refer to the exhibit.

## Fault Properties



**General**

Troubleshooting

History



**Fault Code:** F3208

**Severity:** major

**Last Transition:** 2020-07-07T14:42:49.161+03:00

**Lifecycle:** Soaking

**Affected Object:** edm/Mgr-[UCS\_C1]-UCS\_C1

**Description:** Fault delegate: Connection to External Device: 172.16.105.50 with name UCS\_C1 is failing to connect with the error: [Failed to connect with Integration Manager]. Please verify network connectivity of External Device and that user credentials are valid.

**Type:** Communications

**Cause:** connect-failed

**Change Set:** issues (Old: , New: connection-fault)

**Created:** 2020-07-07T14:42:49.161+03:00

**Code:** F3208

**Number of Occurrences:** 1

**Original Severity:** major

**Previous Severity:** major

**Highest Severity:** major



An engineer fails to implement a Cisco UCS Manager integration manager. The credentials and IP connectivity between Cisco APIC and UCS Manager are configured as expected. Which action resolves the issue?

**Options:**

---

- A- Disable HTTP to HTTPS redirection in Cisco UCS Manager
- B- Enable JSON API on the Cisco UCS Manager
- C- Change the Integration Manager name to FQDN of the Cisco UCS Manager
- D- Install ExternalSwitch app in the APIC controller

**Answer:**

---

D

## Question 5

---

**Question Type: MultipleChoice**

---

Refer to the exhibit.

UCS Central Registration Policy Resolution Control

FSM Status : **In Progress**  
Description :  
Current FSM Name : **Repair Cert**  
Completed at :  
Progress Status :   
Remote Invocation Result : **Resource Unavailable**  
Remote Invocation Error Code : 5  
Remote Invocation Description : **UCSM and UCS Central time is not synchronized. Retrying...**

⊖ Step Sequence

Order	Name	Description	Status	Timestamp	Retried
1	Repair Cert Verify Guid	verifying GUID of UCS Ce...	In Progress		1
2	Repair Cert Unregister		Pending		0
3	Repair Cert Clean Old Data		Pending		0
4	Repair Cert Request		Pending		0
5	Repair Cert Verify		Pending		0

The integration between Cisco UCS Manager and Cisco UCS Central failed. Which action resolves the issue?

**Options:**

- A- Implement the consistent NTP source between the appliances
- B- Implement the connectivity between the appliances through a firewall
- C- Configure the certificate between the appliances
- D- Configure the shared secret key between the appliances

**Answer:**

---

A

## **Question 6**

---

**Question Type: MultipleChoice**

---

Refer to the exhibit.

```

switch1# show vpc consistency-parameters global
Legend:
Type 1 : vPC will be suspended in case of mismatch
Name                               Type      Local Value                               Peer Value
-----
QoS                                  1         ([], [3], [], [], [], [])              ([], [3], [], [], [], [])
Network QoS (MTU)                   1         (9216, 2240, 0, 0, 0, 0)                 (9116, 2240, 0, 0, 0, 0)
Network QoS (Pause)                 1         (F, T, F, F, F, F)                       (F, T, F, F, F, F)
Input Queuing (Bandwidth)           1         (50, 50, 0, 0, 0, 0)                     (50, 50, 0, 0, 0, 0)
Input Queuing (Absolute Priority)    1         (F, F, F, F, F, F)                       (F, F, F, F, F, F)
Output Queuing (Bandwidth)          1         (50, 50, 0, 0, 0, 0)                     (50, 50, 0, 0, 0, 0)
Output Queuing (Absolute Priority)   1         (F, F, F, F, F, F)                       (F, F, F, F, F, F)
STP Mode                            1         Rapid-PVST                               Rapid-PVST
STP Disabled                        1         None                                       None
STP MST Region Name                 1         ""                                         ""
STP MST Region Revision             1         0                                           0
STP MST Region Instance             1
to VLAN Mapping
STP Loopguard                       1         Disabled                                  Disabled
STP Bridge Assurance                1         Enabled                                    Enabled
STP Port Type, Edge                 1         Normal, Disabled                          Normal, Disabled
BPDUFilter, Edge BPDUGuard         1         Disabled                                  Disabled
STP MST Simulate PVST               1         Enabled                                    Enabled
Allowed VLANs                       1, 19, 91, 99, 120, 757-446              1, 10, 19-20, 91, 99, 400-401
                                        451-486, 499, 757, 797                  403, 420, 440, 442, 444
Local suspended VLANs              120

```

The vPC neighborship between two switches is in suspended state. Which configuration change resolves the issue and brings up the vPC neighborship?

### Options:

**A-** Change STP Port Type to Network on the peer switch

- B-** Enable Bridge Assurance on the local switches
- C-** Configure QoS MTU value of 9216 on the peer switch
- D-** Add VLAN 400-401 to the configuration on the local switch

**Answer:**

---

C

**Explanation:**

---

[https://www.cisco.com/c/en/us/td/docs/switches/datacenter/nexus5000/sw/troubleshooting/guide/N5K\\_Troubleshooting\\_Guide/n5K\\_ts\\_vpc.pdf](https://www.cisco.com/c/en/us/td/docs/switches/datacenter/nexus5000/sw/troubleshooting/guide/N5K_Troubleshooting_Guide/n5K_ts_vpc.pdf)

## Question 7

---

**Question Type: MultipleChoice**

---

An engineer is implementing a new BGP peering in their new data center. The engineer set up the BGP session that peers with the remote end. As soon as the BGP peers attempt to exchange routing prefixes, one of the BGP peers drops the connection. After reviewing the configuration, the engineer reviews the logging messages. The engineer discovers that the router is missing keepalives from the remote end and terminates the session. Which action resolves the issue?

**Options:**

---

- A- Set the bgp transport path-mtu-discovery attribute on both peers
- B- Set the higher values for the BGP keepalive and hold-down timers on both peers
- C- Configure the matching BGP AS numbers between the peers
- D- Configure the matching BGP passwords between the peers

**Answer:**

---

B

**To Get Premium Files for 300-615 Visit**

**<https://www.p2pexams.com/products/300-615>**

**For More Free Questions Visit**

**<https://www.p2pexams.com/cisco/pdf/300-615>**

