

Free Questions for HPE7-A07 by vceexamstest

Shared by Randall on 09-08-2024

For More Free Questions and Preparation Resources

Check the Links on Last Page

Question 1

Question Type: MultipleChoice

You are deploying a new AOS 10 mobility gateway cluster. Due to customer requirements, the gateways must be configured with static IP addresses and are restricted from communicating using port 443 to any URLs except tor "central arubanetworks.com"

How would you onboard these gateways successfully into HPE Aruba Networking Central?

A)

Choose Full Setup and Configure:

- · system name
- · switch role
- ACP FQDN address
- · uplink port information
- IP address and default gateway
- DNS IP address
- controller country code
- · timezone and clock
- · admin password

B)

Choose Static Activate and Configure:

- system name
- switch role
- ACP FQDN address
- uplink port information
- IP address and default gateway
- DNS IP address
- · controller country code
- · timezone and clock
- · admin password

C)

controller VLAN uplink port information IP address and default gateway DNS IP address
D)
Choose Static Activate and Configure: controller VLAN uplink port information IP address default gateway DNS IP address
Options:
A- Option A
B- Option B
C- Option C
D- Option D
Answer:
A
Explanation:

Choose Full Setup and Configure:

Option A includes all necessary steps for a full setup of an AOS 10 mobility gateway cluster, including setting the system name, switch role, ACP FQDN address, uplink port information, IP address and default gateway, DNS IP address, controller country code, timezone and clock, and admin password. Since the gateways must have static IP addresses and can only communicate on port 443 for a specific URL, this configuration would need to allow for static IP configuration and restrict communication to the required URL.

Question 2

Question Type: MultipleChoice

Exhibit.

```
Before optimization:
                                               Before optimization
 Status:
                      0x00000000
 Packet Length:
                      1336
 Timestamp:
                      19:34:37.135901600 02/01/2015
 Data Rate:
                      12 6.0 Mbps
 Channel:
                      52 5260MHI 802.11a
 Signal Level:
                      100%
 Signal dBm:
                      -26

→ Noise Level:

                      89%
 Noise dBm:
                      -56
 @ Expert:
                      RIP Packet Out of Sequence
*802.11 MAC Header
 Version:
                      0 [0 Mask 0x03]
 Type:
                      %10 Data [O Mask OxOC]
 Subtype:
                      %0000 Data [0 Mask 0xF0]
Trame Control Flags: $00000010 [1]
                         0... .... Non-strict order
   9
                         .O.. .... Non-Protected Frame
   8
                         .. O. .... No More Data
   0
                         ... 0 .... Power Management - active mode
   9
                         .... O... This is not a Re-Transmission
   0
                         .... .O.. Last or Unfragmented Frame
   0
                         .... ..1. Exit from the Distribution System
   .
                         .... ... O Not to the Distribution System
 Duration:
                       0 Microseconds [2-3]
 Destination:
                       01:00:5E:01:01:01 Mcast IP IANA802:01:01:01 [4-9]
 BSSID:
                       18:64:72:10:BB:31 [10-15]
 Source:
                       D4:61:9D:02:E6:22 [16-21]
 Seq Number:
                       3679 [22-23 Mask OxFFF0]
 Frag Number:
                       0 [22 Mask 0x0K]
After optimization:
                         19:36:23.419826200 02/01/2015 After optimization
  Timestamp:
  Data Rate:
                         600 300.0 Mbps
  G Channel:
                         52 5270MHz 802.11n
3 7 802.11n Flags:
                         .... Reserved
    0
                            .... Short GI
                            .... 40MHz
  Signal Level:
                         100%
  Si: 1 dBm:
                         -29
  Moise Level:
                         868
  Noise dBm:
                         -57
802.11 MAC Header
  Version:
                         0 [0 Mask 0x03]
  Type:
                         %10 Data [O Mask OxOC]
  Subtype:
                         %1000 QoS Data [O Mask OxFO]
Frame Control Flags:
                        %00000010 [1]
                            O... .... Non-strict order
                            .O.. .... Non-Protected Frame
    0
                            .. 0. .... No More Data
                            ... 0 .... Pover Management - active mode
```

A network administrator attempts to improve multicast traffic flow and performs some packet captures for validation What can the network administrator conclude from the results?

Options:

- A- The data rate increased from 6 Mops to 300 Mops because Broadcast Multicast optimization (BCMCO) was configured.
- B- The capture taken after optimization does not show a packet length because Multicast Transmission Optimization was configured.
- C- The type flew remains consistent because Dynamic Multicast Optimization (DMO) was configured.
- D- The data rate increased from 6 Mbps to 300 Mops because Dynamic Multicast Optimization (DMO) was configured.

Answer:

D

Explanation:

Dynamic Multicast Optimization (DMO) is a feature that enhances the delivery of multicast traffic by optimizing the data rate. The before and after optimization images show a significant increase in the data rate, which is a typical result of DMO being configured, as it allows multicast traffic to be transmitted at higher data rates by converting multicast streams into unicast streams for the clients that need them.

Question 3

Question Type: MultipleChoice

After onboarding three new AOS 10 gateways using the full-setup method into the same Central group, a customer cannot log in to one of the gateways using the HPE Aruba Networking Central remote console due to an incorrect password.

Options:

- A- The admin password created using full-setup does not match the global Central admin password.
- B- The admin password created during the run-setup process is not configured to allow me remote console access
- C- The admin password created during the full-setup process does not match the Central group admin password
- D- The admin password created at the Central group level has expired

Answer:

C

Explanation:

When onboarding devices into a centralized management system, each device can have its individual admin password set during the onboarding process. If this password doesn't match what is expected at the group level in the central management platform, login issues such as the one described can occur.

Question 4

Question Type: MultipleChoice

A network technician racked up two 9240 mobility gateways in a single cluster that will be terminating 1700 APs in a medium-sized branch office Next, the technician cabled the gateways with two SFP28 Direct Attach Copper (DAC) cables, distributed between a two-member core switching stack and powered them up.

What must the network administrator do next regarding the gateway configuration to ensure maximum wired bandwidth utilization?

Options:

- A- Map two physical ports to a port channel on each gateway.
- B- Make an ports trunk interfaces and permit data VLANs
- C- Disable the spanning tree and allocate unique VLANs to each port.
- D- Manually set 25Gbps speeds on all ports.

Answer:

Explanation:

To maximize wired bandwidth utilization, especially when multiple APs are terminating on mobility gateways, it's best practice to aggregate physical ports into a port channel. This provides redundancy and increased bandwidth by combining the throughput of multiple ports.

Question 5

Question Type: MultipleChoice

Your customer's employees connected to a wired network are complaining about a poor user experience. The customer has UXI sensors deployed on their premises. These sensors nave been running for multiple months. They are testing both the wired network (using the wired Interface of each sensor) and the wireless networks. Your customer used the UXI dashboard to find the reason for the poor user experience to find more details, the customer asked you to check the packet captures that have been downloaded from the sensors using the UXI dashboard.

From the zip file downloaded from the UXI sensors, you checked the "datagrams" .pcap file, but you were not able to find any issues How can you explain this?

Options:

- A- The 'datagrams- pcap file only contains me successful tests Failed tests are contained in the 'datagrams-failed' .pcap file
- B- The UXI sensor could not upload the latest test results to the cloud, so the packet capture is outdated
- C- The datagrams captured on the physical Ethernet interface are in a different .pcap file.
- D- The default filers of the packet captures do not allow tailed tests to be captured by the sensor

Answer:

Α

Explanation:

It is a common practice to separate successful and failed test results into different files for ease of troubleshooting. If the 'datagrams.pcap' file shows no issues, it's likely because it only contains successful test data, and the failed tests that could explain the poor user experience would be in a different file, such as 'datagrams-failed.pcap.'

Question 6

Question Type: MultipleChoice

An AOS 10 multi-site deployment has sites with AP-only bridged SSIDs and other sites with APs and gateways operating tunneled SSiDs. Client session state sync errors exist between secure lab environments and public -facing areas at several sites.

What is causing the issues?

Options:

- A- The DTLS connections are down between APs in the lab and APs in public areas
- B- The affected clients are associated with an SSID with 11r and 11k disabled.
- C- The sites with issues are the overlay AP with gateway sites because the connection to HPE Aruba Networking central is interrupted
- D- The sites with issues are the AP-only deployments because the connection to HPE Aruba Networking Central is interrupted

Answer:

C

Explanation:

In a multi-site deployment with a mix of bridged and tunneled SSIDs, if there are session sync errors between different areas, it could be due to connectivity issues with the central management platform, which in the case of Aruba, is likely HPE Aruba Networking Central. This interruption could cause inconsistencies in session states across the network.

Question 7

Question Type: MultipleChoice

The ACME company has an AOS-CX 6200 VSF switch slack with an uplink over subscription ratio of 9.6:1. They have indicated that their low-priority TCP traffic has been flagged with a DSCP marking coloring them yellow.

Refer to the exhibit.

DSCP	code_point	local_priority cos	color	name
000000	0	1	green	CS0
000001	1	1	green	
000010	2	1	green	
000011	4	1	green	
000100		1	green	
000101	5	1	green	
000110	6	1	green	
000111	7	1	green	
001000	8	0	green	CS1
001001	9	0	green	-
001010	10	0	green	AF11
001011	11	0	green	
901100	12	0	yellow	AF12
901101	13	0	green	
001110	14	0	yellow	AF13
001111	15	0	green	
010000	16	2 2 2 2 2	green	C52
010001	17	2	green	
910010	18	2	green	AF21
010011	19	2	green	
919199	20	2	yellow	AF22
010101	21	2	green	
010110	22	2	yellow	AF23
919111	23	2	green	
011000	24	2 2 3 3 3 3 3 3 3 3 3 3 3 3	green	CS3
911001	25	3	green	
011010	26	3	green	AF31
011011	27	3	green	
011100	28	3	yellow	AF32
911101	29	3	green	
011110	30	3	yellow	AF33
911111	31	3	green	

```
100000
         32
                                                  CS4
                                         green
100001
         33
                     4
                                         green
100010
                                                  AF41
                                         green
                                         green
         35
100011
100100
         36
                                         yellow
                                                  AF42
100101
         37
                                         green
100110
         38
                                         yellow
                                                  AF43
100111
         39
                     4
                                         green
         40
                                                  CS5
101000
                                         green
101001
         41
                                         green
101010
         42
                     5
                                         green
101011
         43
                     5
                                         green
101100
                     5
                                         green
101101
         45
                     5
                                         green
101110
                     5
                                                  EF
                                         green
101111
         47
                     5
                                         green
110000
         48
                     6
                                         green
                                                  CS6
110001
         49
                     6
                                         green
110010
         50
                     6
                                         green
110011
         51
                     6
                                         green
110100
         52
                     6
                                         green
         53
                     6
110101
                                         green
                     6
110110
         54
                                         green
110111
         55
                     7
                                         green
111000
         56
                                                  C57
                                         green
111001
         57
                                         green
111010
         58
                                         green
111011
         59
                                         green
111100
         60
                                         green
                     7
111101
         61
                                         green
                     7
111110
                                         green
111111
                                         green
```

They are considering adding two more nodes to the stack without adding any additional uplinks due to existing wiring constraints. One of their architects has suggested adding the following configuration:

```
vsf1(config)# qos threshold-profile acmethreshold
vsf1(config-threshold)# queue 5 action wred-resp yellow min-threshold 40 percent max-threshold 80 percent
vsf1(config)# int lag 1
vsf1(config-if)# description uplink-to-collapsed-core
vsf1(config-if)# apply qos threshold-profile acmethreshold
```

What would be the impact of applying the acmethreshold profile as shown? (Select two.)

Options:

- A- All upper-layer protocol traffic egressing LAG1 will be subject to drop probability.
- B- All TCP traffic egressing LAG1 wail be subject to drop probability
- C- Only VoIP packets egressing queue 5 on LAG1 will likely be protected from uplink over-utilization.
- D- VoIP packets egressing any queue on LAG1 will more likely be protected from uplink over-utilization
- E- Yellow-flagged TCP traffic egressing LAG1 will be subject to drop probability

Answer:

A, E

Explanation:

Applying the 'acmethreshold' profile as shown in the exhibit would set a minimum and maximum threshold for queue 0, which affects the drop probability for traffic that exceeds these thresholds. The yellow marking indicates a medium drop precedence, so yellow-flagged traffic would be more likely to be dropped when congestion occurs, and the uplink is over-utilized. This action is intended to protect higher-priority traffic, such as VoIP, by giving it a lower probability of being dropped.

Question 8

Question Type: MultipleChoice

A university owns a campus with several buildings segmented into east and west wings, which are L3 separated. The east wing has 1600 APs. and the west wing has 1200 Aps. Each wing has a single gateway cluster managed by HPE Aruba Networking Central. Each cluster contains one 7210 mobility gateway The gateways are configured with DHCP relay and route all client VLANs. A new business-critical faculty real-time application requires users to roam within wings but not across wings without disconnections or delay increments.

Which changes must the network administrator make lo successfully meet the requirement without performance degradation matching best practices? (Select two.)

Options:

- A- Replace the 7210 mobility gateway in the west wing with a pair of 7030 mobility gateways.
- B- Add a single 7210 mobility gateway to each cluster.
- C- Remove the DHCP relay from the gateways and enable the DHCP server instead
- D- Replace me 7210 mobility gateway in the east wing with a pair or 9012 mobility gateways
- E- Run L2 for all SSIDs and permit the users' VLANs in the gateway's uplinks.

Answer:

B, E

Explanation:

To support a business-critical faculty real-time application that requires seamless roaming within wings without cross-wing roaming, it's essential to ensure high availability and sufficient capacity. Adding an additional 7210 mobility gateway to each cluster would provide the required redundancy and capacity. Running L2 for all SSIDs and permitting user VLANs on gateway uplinks would facilitate the necessary traffic flow without L3 segmentation issues, thus supporting seamless roaming within each wing.

Question 9

Question Type: MultipleChoice

A customer's infrastructure is set up to use both primary and secondary gateway clusters on the SSID profile based on best practices. What is a valid cause tor having an equal spirt in APs connected to the primary and secondary gateway clusters?

Options:

- A- The secondary gateway cluster is heterogeneous
- B- The secondary gateway cluster is homogeneous
- C- The primary gateway cluster is up. out some APs are unable to reach the primary gateway cluster. These APs would connect to the secondary gateway cluster
- D- The primary gateway cluster is up. out some APs cannot reach the secondary gateway cluster. These APs would connect to the secondary gateway cluster

Answer:

С

Explanation:

In a high availability setup where both primary and secondary gateway clusters are present, APs are typically designed to connect to the primary cluster. If the APs are equally split between the primary and secondary, this may indicate that some APs cannot reach the primary cluster due to connectivity issues or reachability constraints, thus falling back to the secondary cluster.

Question 10

Question Type: MultipleChoice

A customer has deployed an AOS 10 mobility gateway cluster consisting of three controllers at a single site The WLAN is configured to tunnel wireless device traffic to the AOS 10 mobility cluster The clients are authenticated by ClearPass using WPA3-Enterprise (opmode wpa3-aes-ccm-128). The security team has requested the ability to force a wireless device to reauthenticate using ClearPass.

Which steps are required to ensure ClearPass can consistently initiate a change of authorization against an AOS 10 mobility cluster, including during gateway failover scenarios? (Select two)

Options:

- A- set cluster mode to Auto Site under High Availability Cluster configuration
- B- modify WLAN SSID VLAN Mode Configuration
- C- enable manual cluster configuration under High Availability Cluster Configuration
- D- enable Dynamic Authorization CoA under High Availability Cluster Configuration
- E- modify NAS IPv4 address under Security Advanced RADIUS Client

Answer:

D, E

Explanation:

To ensure that ClearPass can initiate a Change of Authorization (CoA) consistently, it's important to enable dynamic authorization to allow RADIUS CoA messages to be processed. This setting typically falls under the high-availability cluster configuration to ensure that it persists across gateway failovers. Additionally, the NAS IP address must be configured under RADIUS client settings to ensure that the correct IP address is used for RADIUS communications, which is necessary for CoA to function correctly.

Question 11

in a WLAN network with a tunneled SSID. you see the following events in HPE Aruba Networking Central:

▼ Occurred On ↓	Event Type	Serial	∀ Description ×
Nov 14, 2023, 09:44:40	Client PMK/OKC Key Delete	527]	Operation DEL for key cache entry for client 3:37:18:0d with sequence number 2
Nov 14, 2023, 09:44:04	Client PMK/OKC Key Add/Update	527J	Operation ADD/UPDATE for key cache entry for client 37:18:0d with sequence
Nov 14, 2023, 09:43:41	Client PMK/OKC Key Delete	T2Z8	Operation DEL for key cache entry for client ::48:96:4d with sequence number 73
Nov 14, 2023, 09:43:39	Client PMK/OKC Key Add/Update	T2X7	Operation ADD/UPDATE for key cache entry for client 48:96:4d with sequence
Nov 14, 2023, 09:40:03	Client PMK/OKC Key Add/Update	527J	Operation ADD/UPDATE for key cache entry for client <37:18:0d with sequence
Nov 14, 2023, 09:38:10	Client PMK/OKC Key Delete	527J	Operation DEL for key cache entry for client 37:18:0d with sequence number 2
Nov 14, 2023, 09:37:29	Client PMK/OKC Key Add/Update	527J	Operation ADD/UPDATE for key cache entry for client 20:4c:03:37:18:0d with sequence
Nov 14, 2023, 09:35:16	Client PMK/OKC Key Delete	T2Z8	Operation DEL for key cache entry for client 37:18:0d with sequence number 1
Nov 14, 2023, 09:35:14	Client PMK/OKC Key Add/Update	527]	Operation ADD/UPDATE for key cache entry for client . :37:18:0d with sequence
Nov 14, 2023, 09:32:55	Client PMK/OKC Key Delete	527J	Operation DEL for key cache entry for client 20:4c:03:37:18:0d with sequence number 2
Nov 14, 2023, 09:32:53	Client PMK/OKC Key Add/Update	T2Z8	Operation ADD/UPDATE for key cache entry for client :37:18:0d with sequence

The customer asks you to investigate log messages What should you tell them?

Options:

- A- This indicates a security issue. The client with a MAC address ending with 37 18;0d Is performing a Denial-of-Service attack on your network. You should track down the client and remove it from the network.
- **B-** This is normal, expected behavior. No further actions are needed.

- C. This indicates a client WLAN driver issue for the client with a MAC address ending with 37:18 :Od. You should upgrade the client WLAN driver.
- D- There is a roaming issue Enable Fast Roaming 802.11r and OKC to resolve the issue.

Answer:

В

Explanation:

The event log showing PMK (Pairwise Master Key) and OKC (Opportunistic Key Caching) key add/update and delete operations is indicative of normal client behavior in a WLAN environment. These events are part of the standard process for maintaining client session security and do not necessarily indicate any issue.

Question 12

Question Type: MultipleChoice

A customer is running out of IP addresses in a network segment. What will happen If they add an additional IPsubnet to the same VLAN?

Options:

- A- Broadcasts for me two subnets win arrive on all ports in the same VLAN
- B- IGMP will not work in both of the subnets in the same VLAN
- **C-** This would result in a single SVI using two subinterfaces.
- D- Users can reach each other and establish PTP traffic without passing an L3 point in the same VLAN

Answer:

D

Explanation:

Adding an additional IP subnet to the same VLAN means that devices configured with either subnet can communicate at Layer 2 without the need for routing. This is because they are on the same VLAN and thus in the same broadcast domain. However, to communicate between subnets, an L3 device or inter-VLAN routing would be required.

To Get Premium Files for HPE7-A07 Visit

https://www.p2pexams.com/products/hpe7-a07

For More Free Questions Visit

https://www.p2pexams.com/hp/pdf/hpe7-a07

