Free Questions for H35-211 by certsinside

Shared by Le on 24-05-2024

For More Free Questions and Preparation Resources

Question 1

(single) encounters VoIP service with other vendors' devices. The ONU's RTP temporary terminal resource range setting is inconsistent with the peer softswitch. Which of the following is the fault description?

Options:

A- The user picks up the phone under the ONU.

B- Under the ONU, the caller and the called party are not connected.

C- The ONU makes the caller's off-hook dialing to listen to the busy tone in a random time.

D- Under the ONU, the user makes the caller off-hook without sound.

Answer:

C

Question 2

(multiple) What are the possible positioning methods when the "echo" fault occurs in the VoIP PSTN telephony service?

Options:

A- Check if the acoustic echo is caused by the terminal phone.

B- Check if the PSTN port transmit gain is set too large.

C- Check if the DSP chip input gain (PCM->IP) is set too large.

D- Check if the EC switch (echo suppression switch) of the peer device is turned on during the call.

Answer:

A, B, C, D

Question 3

Question Type: MultipleChoice

(single) For the description of the UA5000, which of the following statements is incorrect?

Options:

A- The UA5000 adopts the same hardware platform and supports PSTN, NGN, IMS and FTTx four networks.

B- UA5000 various traditional private line services under TDM/PSTN.

C- The UA5000 supports ADSL2+ service access.

D- The UA5000 does not support VDSL2 service access.

Answer:

D

Question 4

Question Type: MultipleChoice

(multiple) UA5000 H303ESC EMU status shows what are the possible causes of the failure?

Options:

A- Data configuration error

B- ESC monitoring line sequence error

C- Monitor the wiring device and ESC plug position error

D- ESC board DIP switch setting error

Answer:

A, B, C, D

Question 5

Question Type: MultipleChoice

(single) When upgrading the MA5680T using the command line, you need to restart the system after completing the new file upload.

What operation is generally used when restarting the system?

Options:

A- reboot active

B- reboot standby

C- reboot system

D- All of the above

Answer:

C

Question 6

Question Type: MultipleChoice

(multiple) What remote acceptance functions can the MA5680T provide?

Options:

A- PPPOE simulation test

B- BHCP simulation test

C- Voice call simulation test

D- BTV simulation test

Answer:

A, B, C, D

Question 7

Question Type: **MultipleChoice**

(multiple) Use the pppoe simulate start command to start the ONT PPPoE dial-up emulation test. What needs to be entered?

Options:

A- User name

B- VLAN ID

C- PPPOE password

D- Authentication mode (pap or chap, default chap)

Answer:

A, B, C, D

Question 8

(single) Is the following description correct?

The ADSL port can work in both interleaved and fast channel modes. The fast mode omits the process of interleaving and deinterleaving, so the delay after processing can be greatly reduced. In the case where the ADSL service has a high latency requirement, the interleaving mode can be used.

Options:

A- True

B- False

Answer:

B

Question 9

Single) For the GPON line, the MA5680T supports multiple protection switching modes. Which of the following protection technologies supports the protection of the backbone fiber and the branch fiber at the same time?

Options:

A- Type A

B- Type B

C- Type C

D- Type D

Answer:

C

Question 10

Question Type: **MultipleChoice**

(single) Is the following description correct?

The MA5600T/MA5680T supports traffic shaping for specific service-ports.

Options:

A- True

B- False

Answer:

B

Question 11

Question Type: **MultipleChoice**

(multiple) Regarding the MA5600T/MA5603T Ethernet link aggregation, what are the following statements correctly?

Options:

A- Support cross-board aggregation

B- Supports a maximum of 512 aggregation groups, each of which includes up to 8 physical ports.

C- Support link aggregation in load balancing mode and non-load sharing mode (active/standby mode).

D- Supports manual configuration and static LACP link aggregation. Dynamic LACP link aggregation is not supported.

Answer:

A, B, C, D

Question 12

Question Type: MultipleChoice

(single) When configuring GPON services, which of the following options must be bound to the DBA template to take effect?

Options:

A- Tcont

B- Gemport

C- PON port

D- service-port

Answer:

A

To Get Premium Files for H35-211 Visit

https://www.p2pexams.com/products/h35-211

For More Free Questions Visit

https://www.p2pexams.com/huawei/pdf/h35-211